

FIG. 1  
TEST REPORT

Sample #1 Surface at 40X After  
48 Hours at 150C





FIG. 2 TEST REPORT

Sample 3 Surface Photo 40X  
After 48 Hours at 150C




TO ZOONATE - 6815500

FIG.3

*Sample 3 After 48 Hrs./150C  
Corner of Plaque 40X*

#3 Control 48Hrs./150C  
40X Corner Crazing/Very Bright



Sample 4 Corner Shot 40X  
48 Hours at 150C

#4 Control 48Hrs./150C  
40X Corner crazing/Very Brittle  
Another View




FIG. 5° 6 ASTEROID

Sample 4 Surface Photo 40X  
After 48 Hrs./150C





FIG. 6  
TOZGASTOOT

# Sample 3 versus 4 Corner View After 48hrs./150C



Unwashed Sulfur Black

Washed Sulfur Black